FORM
FIRR
Rev 5/16

State of Colorado Oil and Gas Conservation Commission



Document Number: 401768193

Date Received: 09/19/2018

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109

FIR RESOLUTION FORM

CA Summary:		
5 of 5 CAs from the FIR responded to on this Form		
5 CA Completed 0 Factual Review Request		
OPERATOR INFORM	ATION	
OGCC Operator Number: 76840	Contact Name and Telephone:	
Name of Operator: SCHNEIDER ENERGY SERVICES INC	Name:	
Address: P O BOX 889	Phone: () Fax: ()	
City: FORT MORGAN State: CO Zip: 80701	Email:	
Additional Operator Contact:		
Contact Name Phone Er	mail	
<u>Schneider, Jeff</u> <u>970-867-9437</u> <u>je</u>	ff@schneiderenergy.com	
Bothwell, Kevin 970-867-9437 kt	oothwell@schneiderenergy.com	
Pesicka, Conor	onor.pesicka@state.co.us	
COGCC INSPECTION SUMMARY:		
FIR Document Number:691200347		
Inspection Date: 08/17/2018 FIR Submit Date: 08/18/2018	FIR Status:	
Inspected Operator Information:		
Company Name: SCHNEIDER ENERGY SERVICES INC	Company Number: 76840	
Address: P O BOX 889		
City: FORT MORGAN State: CO Zip: 8070	11	
LOCATION - Location ID: 306577		
Location Name: DRYER-67N60W Number: 14NWNW	County:	
Qtrqtr: NWN Sec: 14 Twp: 7N Range: 60W	Meridian: 6	
Latitude: 40.580720 Longitude: -104.067110		
FACILITY - API Number: 05-12300 Facility ID:	306577	
Facility Name: DRYER-67N60W Number: 14NWNW	_	
Qtrqtr: NWN Sec: 14 Twp: 7N Range: 60W	Meridian: 6	
Latitude: 40.580720 Longitude: -104.067110		
`CORRECTIVE ACTIIONS:		
1 CA# 117990		
Corrective Action: Comply with Rule 210.e using the Rule 210.e guidance document for further details. Date: 10/19/2018		
Response: CA COMPLETED Date of	Completion: 09/17/2018	
Put hazard label on drum		
	_	

Operator Comment:	
COGCC Decision:	Approved
COGCC Representative:	Follow-up Field Inspection Report Doc #696101021 dated 06/12/2019 confirms Legible container label / placarding NOW posted at wellsite. Corrective Action appears addressed.
2 🔽 CA# 11799	1
	Remediate stained equipment; Securely fasten all valves, pipes, and fittings to Date: 09/19/2018 ensure good mechanical condition per Rule 605.d.
Response:	CA COMPLETED Date of Completion: 09/17/2018
Operator Comment:	Washed of pumping unit gearbox
COGCC Decision:	Approved
COGCC Representative:	Follow-up Field Inspection Report Doc #696101021 dated 06/12/2019 confirms Pumpjack gearbox stained with oil NOW appears mitigated. Corrective Action appears addressed.
3 🔽 CA# 11799	2
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details. Date: 09/19/2018
Response:	CA COMPLETED Date of Completion: 09/18/2018
Operator Comment:	Hauled off damaged belt guard
COGCC Decision:	Approved
COGCC Representative:	Follow-up Field Inspection Report Doc #696101021 dated 06/12/2019 confirms unused pumpjack beltguard lying on ground at wellsite NOW removed. Corrective Action appears addressed.
4 🗸 CA# 11799	3
	Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d. Date: 09/19/2018
Response:	CA COMPLETED Date of Completion: 09/18/2018
Operator Comment:	Cleaned up stained soil
COGCC Decision:	Approved
COGCC Representative:	Follow-up Field Inspection Report Doc #696101021 dated 06/12/2019 confirms stained soil around pumpjack gas engine base NOW appears mitigated. Corrective Action appears addressed.
5 🔽 CA# 11799	4
	Plumb bradenhead to surface; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d. Date: 09/19/2018
Response:	CA COMPLETED Date of Completion: 09/18/2018
Operator Comment:	Pumped bradenhead to surface.
COGCC Decision:	Approved
	Follow-up Field Inspection Report Doc #696101021 dated 06/12/2019 confirms Bradenhead NOW appears

OPERATOR COMMENT AND SUB	<u>MITTAL</u>	
Comment:		
I hereby certify that the statem complete.	nents made in this form are, to the best of my knowledge, true, correct, and	
Print Name: Kevin Bothwell	Signed:	
Title: Employee	Date: 9/19/2018 1:51:07 PM	

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (http://ogccweblink.state.co.us/) - Search by Document Number.

<u>Document Number</u>	Description
401768193	FIR RESOLUTION SUBMITTED
401768219	Photos of Dryer site

Total Attach: 2 Files

COGCC plumbed to surface.

Representative: Corrective Action appears addressed.