

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402154815
Date Received:
08/25/2019

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 66561

Name of Operator: OXY USA INC

Address: PO BOX 27757 #110

City: HOUSTON State: TX Zip: 77227-7757

Contact Name and Telephone:

Name:

Phone: () Fax: ()

Email:

Additional Operator Contact:

Contact Name

Phone

Email

Dittrich, Wade

575-390-2828

Wade_Dittrich@Oxy.com

Montgomery, Kelley

Kelley_Montgomery@oxy.com

Rapp, Veronica

832-465-8788

veronica_rapp@oxy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901091

Inspection Date: 08/01/2019

FIR Submit Date: 08/05/2019

FIR Status:

Inspected Operator Information:

Company Name: OXY USA INC

Company Number: 66561

Address: PO BOX 27757 #110

City: HOUSTON State: TX Zip: 77227-7757

LOCATION - Location ID: 437155

Location Name: Sheep Mountain Unit Number: 1-12-B County: HUERFANO

Qtrqr: SESW Sec: 1 Twp: 28S Range: 70W Meridian: 6

Latitude: 37.636890 Longitude: -105.171290

FACILITY - API Number: 05-055-00 Facility ID: 437156

Facility Name: Sheep Mountain Unit Number: 1-12-B

Qtrqr: SESW Sec: 1 Twp: 28S Range: 70W Meridian: 6

Latitude: 37.636890 Longitude: -105.171290

CORRECTIVE ACTIONS:

1 ☒ CA# 128925

Corrective Action: Install sign to comply with Rule 210.e.

Date: 09/06/2019

Response: CA COMPLETED

Date of Completion: 08/19/2019

Operator Comment: Well sign was reinstalled to comply with Rule 210.e.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 128926

Corrective Action: Comply with Rule 1003 f. and perform noxious weed control.

Date: 08/19/2019

Response: CA COMPLETED

Date of Completion: 08/21/2019

Operator
Comment: Canada thistle found in the vegetated areas around the well pad were cut, bagged and treated. Weed treatment was conducted on the roadsides leading to Drill Site 5.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Well sign was reinstalled to comply with Rule 210.e., Canada thistle found in the vegetated areas around the well pad were cut, bagged and treated. Weed treatment was conducted on the roadsides leading to Drill Site 5.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Veronica Rapp

Signed: _____

Title: Biologist

Date: 8/25/2019 11:25:36 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402154815	FIR RESOLUTION SUBMITTED
-----------	--------------------------

402154821	SMU 1-12 well sign
-----------	--------------------

Total Attach: 2 Files