

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402113230

Date Received:

07/18/2019

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beebe, Sabre</u>		<u>sabre.beebe@bpx.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 695100646  
Inspection Date: 05/16/2019 FIR Submit Date: 05/16/2019 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

**LOCATION - Location ID: 333625**

Location Name: JONES-M34N8W Number: 16SWSE County: LA PLATA  
Qtrqtr: SWSE Sec: 16 Twp: 34N Range: 8W Meridian: M  
Latitude: 37.186900 Longitude: -107.721143

**FACILITY - API Number: 05-067-00 Facility ID: 216088**

Facility Name: JONES Number: 34-16 1  
Qtrqtr: SWSE Sec: 16 Twp: 34N Range: 8W Meridian: M  
Latitude: 37.186900 Longitude: -107.721143

**CORRECTIVE ACTIIONS:**

1  CA# 125526

Corrective Action: COMPLY WITH RULE 603.f.

Date: 06/21/2019

Response: CA COMPLETED Date of Completion: 06/12/2019

Operator Comment: All unused equipment removed from location see attached.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**2**  CA# 125527

Corrective Action: Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907"

Date: 06/21/2019

Response: CA COMPLETED

Date of Completion: 06/12/2019

Operator Comment: Impacted materials removed from location and disposed of at the IEI soil box to be remediated in batch. See attached. Operator performed maintenance on equipment.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**3**  CA# 125528

Corrective Action: Provide COGCC with documentation showing approval of use of vacuum pump.

Date: 06/05/2019

Response: CA COMPLETED

Date of Completion: 06/05/2019

Operator Comment: refer to FIRR form 402064919 for previous reporting on this CA.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**4**  CA# 125529

Corrective Action: Install or repair required BMPs to prevent erosion from occurring outside of BMP'S per Rule 1002.f.

Date: 06/21/2019

Response: CA COMPLETED

Date of Completion: 06/12/2019

Operator Comment: wattles removed from location and areas where wattles were have been raked out and seeded to establish vegetation for stabilization of these areas. See attached.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: All corrective actions completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 7/18/2019 10:12:39 AM

## ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402113230	FIR RESOLUTION SUBMITTED
402113550	Work completion photos

Total Attach: 2 Files