



00228001

MEMO

18
Field Trip - March 7, 1955 - D. V. Rogers

Eisenhower Drilling Co.

#1 Whittenbaugh - Section 3, 7N 54W

Inspected well site. Parkersburg pumping unit still standing. Two tanks are standing. Sucker rods are lying on ground. Farm hand said a treater had been removed, and no oil produced in over a year. Well has not been plugged.

Eisenhower Drilling Co.

#1 Ralph Allen - Section 10, 7N 59W

Inspected well site. Production casing is still in the hole. The well is not plugged. A metal can has been placed over the casing. The line from the well to the treater and the tanks have been removed. The treater is still standing. There are three locations that have not been cleaned up, and levelled. The tank outfit removed the tanks.