

TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189



**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 36NWNW  
Location # 335189**



**Sediment build up in ditch.**



**Erosion breach of ditch wall.**