







Tank capacity on label on 300 bbl tank is too small and faded to read at distance.







Washing and riling around separators.







Channeling through berm at entrance of location.







Out let of channel

