

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402466708

Date Received:

08/14/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Kellerby, Shaun

shaun.kellerby@state.co.us

Inspection, Terra TEP

970-285-9377

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 701100203

Inspection Date: 08/12/2020

FIR Submit Date: 08/13/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335392

Location Name: PA-66S95W Number: 33SWNE County: _____

Qtrqtr: SWNE Sec: 33 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.483529 Longitude: -107.999723

FACILITY - API Number: 05-045-00 Facility ID: 335392

Facility Name: PA-66S95W Number: 33SWNE

Qtrqtr: SWNE Sec: 33 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.483529 Longitude: -107.999723

CORRECTIVE ACTIONS:

1 ☒ CA# 141210

Corrective Action: Repair and maintain lease road to comply with rule 204.

Date: 11/14/2020

Response: CA COMPLETED

Date of Completion: 08/14/2020

Operator Comment: Rule 204 states that COGCC has "... the right at all reasonable times to go upon and inspect any oil or gas property." The reclaimed road leading to the well heads do not prevent or exclude COGCC from entering upon or inspecting any of the equipment at this location. The current access road is well maintained and allows access to the well heads by parking at the separators and walking a short distance (approximately 60 paces) to the north. There is nothing in Rule 204 that requires the operator to open a reclaimed road that is not needed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The main access road passes by the separators for this location and provides sufficient access to all equipment associated with this location. The well heads are easily accessed by parking at the separators and walking a very short distance north to the well heads (see attached photo). Per Rule 204, the site and all equipment are open to, and available to COGCC for inspection at any time.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental

Date: 8/14/2020 9:50:43 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402466708	FIR RESOLUTION SUBMITTED
402466732	Photo showing distance from well head to seperators

Total Attach: 2 Files