

Location			
Lease Road:			
Type	Access		
comment:	location is in a pasture and has a 2 track access and is overgrown with weeds		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	unused Pump Jack		
Corrective Action:	Comply with Rule 606		Date: <u>08/13/2021</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Ag fence		
Corrective Action:			Date:
Equipment:			
Type: Pump Jack	# 1		corrective date
Comment:	dissassembled and unused		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:	<input type="text"/>		
Corrective Action:			Date:
Flaring:			

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 242449 Type: WELL API Number: 123-10240 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment: TA
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/13/2020 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 8/17/2021 at approximately 1055 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: This is a inspection to Doc # 699303810. Any corrective actions from previous inspections that have not been addressed are still applicable. Leonard 24-21 at API #05-123-10240 in Weld County Colorado. While there, I observed a wellsite, TA at time of inspection. During this inspection the following possible compliance issues were observed and is now delinquent: 606 Housekeeping: unused pump jack equipment on location, CA date 8-13-2021. See photos 3, 4 & 5. During this inspection the following possible compliance issue have been addressed: 606 Housekeeping: Tumble weeds piled up around WH appear to have been cleaned up. See attached photos. Location: dry, Weather: clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	08/17/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402783452	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5508697
699304244	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5508692