

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/23/2021

Submitted Date:

09/23/2021

Document Number:

690202091

FIELD INSPECTION FORM

Loc ID 309256 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD State: CO Zip: 8111-

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fitzgerald, Edie		efitzgerald@ogrisop.com	
Mack, Ronnie		rmack@ogrisop.com	
ATWATER BONNIE		batwater@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290789	WELL	PR	12/21/2007	GW	071-09301	HILL RANCH 25-16	RI

General Comment:

[This is a Stormwater Management Inspection.](#)
[See attached photos and additional details within this report.](#)

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: There are areas of the main road that are eroded and not stabilized. There is rocks and sediment deposited on the road. There is a cattle guard along the main road that is in disrepair.						Date: <u>10/15/2021</u>
Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments

Comment	User	Date
This inspection was only performed along the main road and not at the well site.	CostaR	09/23/2021
The same inspection of the main road issues will be sent to both Operators that utilize the main access road.	CostaR	09/23/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402821408	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5539359
690202092	Inspection Photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5539350