

GOLDEN EAGLE MINE GE-63-92 API# 05-071-06408 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: MAY 10, 2022
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT #690202809



PHOTO 1: THE TIRE RUTS AND RILLING HAVE BEEN HAND RAKED.

GOLDEN EAGLE MINE GE-63-92 API# 05-071-06408 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: MAY 10, 2022
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT #690202809



PHOTO 2: THE TIRE RUTS AND RILLING HAVE BEEN HAND RAKED.

GOLDEN EAGLE MINE GE-63-92 API# 05-071-06408 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: MAY 10, 2022
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT #690202809



PHOTO 3: THE TIRE RUTS AND RILLING HAVE BEEN HAND RAKED. THE DIVERSION DITCH HAS ALSO BEEN CLEANED OF SEDIMENT AND REDIFIED TO DIVERT STORMWATER TO THE ROCK SPILLWAY.

GOLDEN EAGLE MINE GE-63-92 API# 05-071-06408 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: MAY 10, 2022
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT #690202809



PHOTO 4: THE BARE AREA OF THE LOCATION HAS BEEN SEEDED BY HAND BROADCAST USING AN APPROVED CPW SEED MIX TO PROMOTE THE ESTABLISHMENT OF VEGETATION.