

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403080036

Date Received:
06/15/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Romana Cowden

720-951-5895

cogcc.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800153

Inspection Date: 04/21/2022

FIR Submit Date: 04/26/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335228

Location Name: BENZEL DISPOSAL-66S93W Number: 36NWNE County: _____

Qtrqr: NWNE Sec: 36 Twp: 6S Range: 93W Meridian: 6

Latitude: 39.488510 Longitude: -107.721330

FACILITY - API Number: 05-045- -00 Facility ID: 335228

Facility Name: BENZEL DISPOSAL-66S93W Number: 36NWNE

Qtrqr: NWNE Sec: 36 Twp: 6S Range: 93W Meridian: 6

Latitude: 39.488510 Longitude: -107.721330

CORRECTIVE ACTIONS:

1 ☒ CA# 161289

Corrective Action: Corrective Action #1: Conduct weed management to prevent further establishment and spread of noxious weeds in accordance with Rule 1003.f by 5/26/2022. Ongoing weed management is required until location passes final reclamation.

Date: 05/26/2022

Corrective Action #2: In accordance with Rule 1003; Remove unused concrete forms and reduce and reclaim areas no longer needed for production, including, but not limited to areas at the southeast of the pad, surrounding the concrete forms. Reclamation activities shall be completed no later than 5/26/2022.

Corrective Action #3: Address subsidence occurring in the eastern interim areas of the Location in accordance with Rules 1003 and 602.c. by 5/26/2022.

Response: CA COMPLETED

Date of Completion: 06/09/2022

Operator Comment: Removed concrete forms. NOTE: Holy Cross has a concrete electrical vault in place and it is in use. Also filled subsidence and graded pad surface, and weeds were treated.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 6/15/2022 10:06:38 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

403080036	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files