

Inspection Photos and Issue Report

7/14/2022

Operator: CHEVRON USA INC #16700

Location #324351

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location #324351



Photo 1: Photos 1-2 taken from the north end of the production pad. Photos provide an overview of the Location facing southeast, southwest, west to north.

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location #324351



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location #324351



Photo 3: Photos show emergency contact information on sign is no longer legible.



Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location #324351



Photo 4: Photos taken from the interim areas on the west end of the Location. Photo shows areas not needed for production have been reclaimed. Overall reclamation is “in process”, however there are areas that do not appear to be progressing towards Rule 1003 uniform revegetation standards.

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location #324351



Photo 5: Photos taken from the interim areas on the west end of the Location. Photo shows areas not needed for production have been reclaimed. Overall reclamation is “in process”, however there are areas that do not appear to be progressing towards Rule 1003 uniform revegetation standards.

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location #324351



Photo 6: Photo shows adjacent reference areas.

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location #324351



Photo 7: Photo shows single marked anchor observed on the Location. Unclear if this is the only anchor remaining on the Location, or if remaining anchors have been buried and can't be located. Ensure anchors on Location are marked per 1003 requirements, if remaining anchor is no longer necessary, it should be removed in accordance with Rule 606.

