

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403217783

Date Received:
11/03/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10611
Name of Operator: LONGS PEAK RESOURCES LLC
Address: 2727 ALLEN PARKWAY SUITE 1850
City: HOUSTON State: TX Zip: 77019

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Brandi Terry</u>	<u>8327480912</u>	<u>brandi.terry@boomtownoil.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 697504028
Inspection Date: 06/16/2022 FIR Submit Date: 07/12/2022 FIR Status: _____

Inspected Operator Information:

Company Name: LONGS PEAK RESOURCES LLC Company Number: 10611
Address: 2727 ALLEN PARKWAY SUITE 1850
City: HOUSTON State: TX Zip: 77019

LOCATION - Location ID: 452516

Location Name: Oxnard East Number: 0607-8CH County: _____
Qtrqr: SESE Sec: 31 Twp: 12N Range: 66W Meridian: 6
Latitude: 40.958630 Longitude: -104.812780

FACILITY - API Number: 05-123-00 Facility ID: 452516

Facility Name: Oxnard East Number: 0607-8CH
Qtrqr: SESE Sec: 31 Twp: 12N Range: 66W Meridian: 6
Latitude: 40.958630 Longitude: -104.812780

CORRECTIVE ACTIONS:

1 CA# 163290

Corrective Action: Operator shall redo the revegetation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use the approved seed mixture provided by the surface owner. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management.
Revegetation activities shall be complete no later than 11/21/22 or as soon as environmental conditions will permit.

Date: 11/21/2022

Response: CA COMPLETED Date of Completion: 10/29/2022

Operator Comment: CB Services completed the re seeding corrective action using the attached approved seed mixture. Photos are attached of the completed job.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been completed from the 6/16/2022 Inspection.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brandi Terry

Signed: _____

Title: Regulatory Manager

Date: 11/3/2022 10:43:36 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403217783	FIR RESOLUTION SUBMITTED
403217992	Corrective Action Photos
403218008	Seeding Mixture

Total Attach: 3 Files