

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/20/2022

Submitted Date:

12/20/2022

Document Number:

707900374**FIELD INSPECTION FORM**Loc ID 322229 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 44390Name of Operator: JAVERNICK OILAddress: 3040 E MAINCity: CANON CITY State: CO Zip: 81212**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
Costa, Ryan		ryan.costa@state.co.us	
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210062	WELL	SI	03/01/2020	OW	043-06141	FLORENCE 33-1	PR

General Comment:[Follow up inspection per Doc#s 690202374 and 690203637. This is the third inspection were corrective actions have not been addressed.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s)		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	12/09/2022

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Tank on south side of location		
Corrective Action:	Tank is unused equipment and cannot be stored on location. Comply with rule 606	Date:	12/09/2022

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	The cattle panels around the pumpjack have fallen over.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	12/09/2022

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 210062 Type: WELL API Number: 043-06141 Status: SI Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday December 20, 2022 at approximately 8:57AM, I, Inspector Randy Silver, conducted an on-site re-inspection Per doc #'s 690202374 and 690203637.</p> <p>Location: Florence #33-1</p> <p>Operator: Javernick Oil</p> <p>API#: 043-06141</p> <p>County: Freemont</p> <p>While there, I observed a producing in well and Tank Battery</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Sign: Rule 605d Corrective action date of 12-9-22</p> <p>Unused equipment: Rule 606 Corrective action date of 11-18-21 and 12-09-22</p> <p>Fencing: Rule 1002 Corrective action date of 12-09-22</p> <p>Weather conditions: Clear</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverrr	12/20/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
707900375	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5953066