



DEPARTMENT OF NATURAL RESOURCES

Roy Romer, Governor

1120 Lincoln St., Suite 801

Denver, CO 80203

Phone: (303) 894-2100

FAX: (303) 894-2109

WELL: CGF Windsong #4 SENW 11 19S 45W Kiowa County, CO.

COMPLETION SUMMARY: Drilled 11/87; 8 5/8" surface casing to 370' KB; 5 1/2" 14# production casing to 4955'; CIBP at 4295'; perforations unknown.

FIELD INSPECTION SUMMARY: Open Casing, no tubulars; no production equipment.

PLUGGING PROCEDURES:

** Contact landowner prior to MIRU

1) MIRU; With wireline unit set CIBP at 4020' and dump 2 sks cement on top.

2) Dig fluid retaining pit as necessary; load hole with water.

3) Set plugs at the following depths:

Plug #1: Perforate at 1250' and balance 100 sks cement in and out of 5 1/2" casing

Plug #2: Perforate at 410' and balance 40 sks cement in and out of 5 1/2" casing

3) Set 10 sks cement at top of casing strings, cut 4' below GL, weld on plate.

4) Backfill cellar, any pit dug, and restore well site to original condition, including ripping and reseed of well site and lease road.