

Document Number:
403244134

Date Received:
11/30/2022

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 100322 Contact Name: Kevin Monaghan
 Name of Operator: NOBLE ENERGY INC Phone: (970) 3812990
 Address: 2001 16TH STREET SUITE 900 Fax: _____
 City: DENVER State: CO Zip: 80202 Email: kevin.monaghan@chevron.com

For "Intent" 24 hour notice required, Name: Carlile, Craig Tel: (970) 484-3494
COGCC contact: Email: craig.carlile@state.co.us

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-123-26213-00
 Well Name: DECHANT Well Number: 21-25
 Location: QtrQtr: SENW Section: 25 Township: 3N Range: 65W Meridian: 6
 County: WELD Federal, Indian or State Lease Number: _____
 Field Name: WATTENBERG Field Number: 90750

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.198153 Longitude: -104.614694
 GPS Data: GPS Quality Value: 3.6 Type of GPS Quality Value: PDOP Date of Measurement: 11/25/2008

Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7212	7226	07/30/2018	B PLUG CEMENT TOP	6926
NIOBRARA	6976	7096	07/30/2018	B PLUG CEMENT TOP	6926
J SAND	7688	7722	07/26/2018	B PLUG CEMENT TOP	7639

Total: 3 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J66	24	0	772	400	772	0	VISU
1ST	7+7/8	4+1/2	180	11.6	0	7846	590	7846	3702	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7638 with 20 sacks cmt on top. CIBP #2: Depth 6926 with 20 sacks cmt on top.
 CIBP #3: Depth 4239 with 2 sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 35 sks cmt from 2400 ft. to 1939 ft. Plug Type: CASING Plug Tagged:
 Set 195 sks cmt from 1768 ft. to 1261 ft. Plug Type: OPEN HOLE Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 2500 ft. with 155 sacks. Leave at least 100 ft. in casing 2400 CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 (Cast Iron Cement Retainer Depth)

Set 324 sacks half in. half out surface casing from 972 ft. to 80 ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 1768 ft. of 4+1/2 inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: 47
 Surface Plug Setting Date: 09/14/2022 Cut and Cap Date: 10/31/2022

*Wireline Contractor: APLUS *Cementing Contractor: APLUS

Type of Cement and Additives Used: Class G Neat

Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

Perfs @ 2500' and 2000' for CICR @ 2400'
 Cut/Pull CSG @ 1768'

Form 5A (CIBPs) DocNum: 401885697
 Form 17 DocNum: 403167280
 Form 27 DocNum: 403150060
 Form 42 DocNum: 403156474
 Form 44 DocNum: Flowline will be abandoned

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Lauren Hoff
 Title: HSE Reg Affairs Coord Date: 11/30/2022 Email: DenverRegulatory@chevron.onmicrosoft.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric Date: 2/14/2023

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

0 COA	

Attachment List

Att Doc Num

Name

403244134	FORM 6 SUBSEQUENT SUBMITTED
403244152	CEMENT JOB SUMMARY
403244153	OPERATIONS SUMMARY
403244154	WELLBORE DIAGRAM
403244158	WIRELINE JOB SUMMARY

Total Attach: 5 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)