

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2023

Submitted Date:

07/19/2023

Document Number:

702501661

FIELD INSPECTION FORM
 Loc ID 315170 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 34720

Name of Operator: GORDON ENGINEERING INC

Address: PO BOX 113

City: SPRINGDALE State: UT Zip: 84767

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Bryan, Nicholas	(385) 250-4548	nickbryan85@gmail.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
103788	PIT	AC	09/16/2022		-	FEDERAL 10-4 SEPARATOR	AC
230362	WELL	PR	10/01/2021	GW	103-08024	FEDERAL 10-4	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday, 7/19/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Gordon Engineering Inc on the Federal 10-4 well, Location #315170, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with Black Bear, High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Inspection #702501359 on 5/18/23. All Corrective Actions are still unresolved and previous due dates will remain.

While there during normal operations the following compliance issues were observed:

1. Weeds.
2. Bradenhead still inaccessible or not visible.
3. Gas meter calibration still not visibly displayed.
4. Stormwater BMPs have not been implemented.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	(970) 618-0811 or 911
Corrective Action:	
Date:	

Good Housekeeping:			
Type	WEEDS		
Comment:	Oil and Gas Locations will be kept free of all Undesirable Plant Species.		
Corrective Action:	Maintain noxious weed control on all disturbed areas as a result of Oil & Gas activities.	Date:	07/27/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:	Livestock wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 0		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow Bradenhead visual inspection.	Date:	05/29/2023
Type: Deadman # & Marked	# 3		
Comment:	2 damaged		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration not visibly displayed.		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.		Date: 05/29/2023
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	103788	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	AC
Facility ID:	230362	Type:	WELL	API Number:	103-08024	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:					Date:				

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater BMPs need implementation and maintenance.

Corrective Action: Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 06/19/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 103788 Lat: 39.886953 Long: -108.725361

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action

Date: _____

Fencing:

Fencing Type: Livestock Fencing Condition: _____

Comment: _____

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: _____

Corrective Action

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
403470467	INSPECTION SUBMITTED	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6188202
702501666	Inspection Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6188197