

15444 Federal Building
Denver, Colorado 80202

March 20, 1967

Mr. Jim K. Get
9965 MacArthur Blvd.
Oakland, California 94605

Dear Mr. Get:

Responding to your letter of March 16, our records show that Jack White Drilling Company drilled three wells on Denver 033804(b), SE $\frac{1}{4}$ SE $\frac{1}{4}$ sec. 11, T. 1 N., R. 102 W., 6th P. M., Rangely field, Colorado. All operations resulted in completions of dry holes or failures and no production has ever been reported from this portion of the lease.

Drilling information reported on these wells are submitted for your record:

<u>Well No.</u>	<u>Spud Date</u>	<u>Abd Date</u>	<u>Total Depth</u>
1	7/17/56	9/20/56	3,200'
5	9/24/56	6/17/57	3,205'
6	10/ 6/56	11/ 4/56	2,560'

We are returning your photocopy records of the partial assignments of operating interests.

Sincerely yours,

E. R. Haymaker
District Engineer

Enclosures 2