

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/21/2023

Submitted Date:

09/21/2023

Document Number:

702501894

FIELD INSPECTION FORM

Loc ID: 313094 Inspector Name: Burchett, Kirby On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10428
Name of Operator: DIVERSIFIED ENERGY LLC
Address: 19501 E MAIN STREET #200
City: PARKER State: CO Zip: 80138

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Haack, Denise	(303) 507-7437	dhaack@oagproduction.com	
Pesicka, Conor	(303) 894-2100, Ext 5164	conor.pesicka@state.co.us	
Haack, Jason	(303) 719-4094	jhaack@oagproduction.com	

General Comment:

[ECMC Inspection Report Summary](#)

On Thursday, 09/21/2023, Inspector Kirby Burchett, attempted to conduct a follow up field inspection at Diversified Energy LLC on the Bingman 1-14 well, Location #313094, in Moffat County, Colorado. This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

During this attempted inspection the following compliance issues were observed,

- 1. Access road gate locked.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Location entrance sign with operator contact information. Called 303-995-0826 at 09:12 hours. 9 hours later still no response		
Corrective Action:	Provide key, combinations, or alternate method of access to comply with rule 204.	Date:	09/22/2023

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403538089	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6260298
702501896	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6260293