

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/21/2023

Submitted Date:

09/22/2023

Document Number:

699107428

FIELD INSPECTION FORM

Loc ID 327367 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 10 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
327367	LOCATION	AC			-	BLANCHE-62N62W 20NWNW	SI

General Comment:

[Inspection of the location](#)

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Pit appears to have weathered capacity/NFPA Placard. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	10/12/2023
Type	BATTERY		
Comment:	Missing battery sign. See attached photos.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	10/12/2023

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Good Housekeeping:

Type	WEEDS		
Comment:	Overgrown Vegetation in multiple spots on location, needs to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606.	Date:	10/12/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Deadman # & Marked	# 3	Overgrown Vegetation is covering them.			
Type: Gas Meter Run	# 1				
Type: Bird Protectors	# 1				
Type: Horizontal Heated Separator	# 1				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1				40.129200,-104.355200

Comment:	Updated the status of the pit #102744 with a form 15.	
Corrective Action:	Updated facility record per rule 909.a	Date: 10/12/2023

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 327367 Type: LOCATION API Number: - Status: AC Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Appears to have plant die-off, submit a form 27 to investigate. See attached photos

Corrective Action: Comply with rule 901.a Date: 10/12/2023

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Thursday 9/21/23 at approximately 0955hrs I, Inspector Adam Burns, Conducted an on-site inspection at Blanche-62N62W 20NWNW of KP Kaufman Company INC. Location ID #327367 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Overgrown Vegetation in multiple spots on location, needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 10/12/23 Missing battery sign. Install sign to comply with Rule 605.e. With a Corrective Action date of 10/12/23 Pit appears to have weathered capacity/NFPA Placard. Install sign to comply with Rule 605.h. With a Corrective Action date of 10/12/23 Updated the status of the pit #102744 with a form 15. Updated facility record per rule 909.a. With a Corrective Action date of 10/12/23 Appears to have plant die-off, submit a form 27. Comply with rule 901.a. With a Corrective Action date of 10/12/23 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	burnsa	09/22/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403538506	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6260859
699107429	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6260846
699107430	Annotation Report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6260848
699107431	Issues Report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6260849