

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2023

Submitted Date:

09/26/2023

Document Number:

695108708

**FIELD INSPECTION FORM**Loc ID 324505 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 66561

Name of Operator: OXY USA INC

Address: PO BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	<a href="#">All Inspections</a>
Sanchez, Chris		chris.sanchez@state.co.us	
Costa, Ryan		ryan.costa@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211864	WELL	SI	08/01/2020	GW	055-06102	SHEEP MOUNTAIN UNIT 12-2-E	SI

**General Comment:**

Inspected Facilities									
Facility ID:	211864	Type:	WELL	API Number:	055-06102	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: WELL IS P&A									
Corrective Action: _____ Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: PHOTO 3: It appears the well was plugged and abandoned on 8/9/2022. There is an open excavation at the wellhead from an active remediation that is still ongoing. The wellhead will need to be cut and capped deep enough to allow recontouring back to the original grade. There is a lined pit at the wellsite that should have been closed within 3 months of abandonment (11/9/2022).

Corrective Action: **Comply with 1004 Rules, IMMEDIATE ACTION IS REQUIRED.**

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: YES Pit ID: \_\_\_\_\_ Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: Adequate

Comment: **NO PIT PERMIT IN ECMC FILE**

Corrective Action: **CONTACT AREA EPS**

Date: 09/28/2023

**Fencing:**

Fencing Type: Wildlife Fencing Condition: Adequate

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: YES Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #690204286, IT DOES NOT APPEAR THAT ANY ACTION HAS BEEN TAKEN TO RESOLVE CORRECTIVE ACTION FROM PREVIOUS INSPECTION. IMMEDIATE ACTION IS REQUIRED.	beardslt	09/26/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403545351	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6268435">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6268435</a>
695108709	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6268420">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6268420</a>