

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/09/2023

Submitted Date:

10/11/2023

Document Number:

699107558

**FIELD INSPECTION FORM**

Loc ID: 332047 Inspector Name: Burns, Adam On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 65110  
Name of Operator: O'BRIEN ENERGY RESOURCES CORP  
Address: 18 CONGRESS ST STE 207  
City: PORTSMOUTH State: NH Zip: 03801

**Findings:**

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
332047	LOCATION	AC			-	LOST CREEK-63N62W 21SWNW	SI

**General Comment:**

This is a follow up to prior inspection document #699107148. CA's were not corrected.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Pit needs NFPA placard. See attached photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/22/2023

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

**Good Housekeeping:**

Type	WEEDS		
Comment:	Overgrown vegetation is starting to grown in the tank battery and needs to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606.	Date:	09/22/2023
Type	TRASH		
Comment:	Unused Fence post needs to be removed for good housekeeping. See attached photo		
Corrective Action:	Comply with Rule 606.	Date:	09/22/2023

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 332047 Type: LOCATION API Number: - Status: AC Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI Tank Battery  
No FIRR was submitted.

Corrective Action: When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b.

Date: 10/13/2023

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On Monday 10/9/23 at approximately 0957hrs I, Inspector Adam Burns, Conducted an on-site inspection to prior inspection document #699107148 at Lost Creek-63N62W 21SWNW Tank Battery of O'Brien Energy Resources Corp. Location ID #332047 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      Pit needs NFPA placard. Install sign to comply with Rule 605.h. With a Corrective Action date of 9/22/23                      Overgrown vegetation is starting to grown in the tank battery and needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23                      Unused Fence post needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23                      No FIRR was submitted. When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b. With a Corrective Action date of 10/13/23                      No CA's were corrected                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of the inspection report.</p>	burnsa	10/11/2023

**Attached Documents**

You can go to COGCC Images (<https://ogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403557345	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281164">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281164</a>
699107559	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281138">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281138</a>