

**COLORADO OIL & GAS CONSERVATION COMMISSION**  
**FIELD INSPECTION REPORT**



00041837

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- <u>123 - 08847</u>		LEASE NAME: <u>Schubert #2 42-13</u>	
LOCATION: <u>SENE-S13-IN-68W</u>		OPERATOR: <u>Union Pacific, Inc</u>	
DATE: <u>11-14-1995</u>		INSPECTOR: <u>Mike Havelka</u>	
Insp. Type: <u>PK</u>	Insp. Status: <u>STA</u>	PA: Y    N	Pass/Fail: P    F    Viol.: Y    N    NOV: Y    N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210)	<u>up</u>	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904)		
<b>Fences</b> (Rule 604.C.(3), 1003.A)		
<b>Tank Battery Equipment</b> (Rule 604)	<u>OK</u>	
<b>Fire Walls/Berms/Dikes</b> (Rule 604)		
<b>General Housekeeping</b> (Rule 603.G)	<u>OK</u>	
<b>Spills (Oil/Water)</b> (Rule 908)		
<b>Bradenhead</b> (Rule 207)		
<b>Drilling Well/Workover</b> (Rule 315)		
<b>Surface Rehabilitation</b> (Rule 317)		
<b>Miscellaneous</b>		

<b>CORRECTIVE ACTION REQUIRED:</b> <u>Land owner complained of no production in three years wants wells removed - No production in over 2 years</u>
Date Corrective Action Required By: _____ Date Remedied: <u>MIT/PA letter sent 11/17/95</u>

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File    Green - Operator    Canary - Well Site

WOAO rescinded