



00041840

COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT



<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
API No. 05- <u>123 - 08847</u>		LEASE NAME: <u>Schubert #2 42-13</u>	
LOCATION: <u>SENE-S13-1N-68W</u>		OPERATOR: <u>Union Pacific Res</u>	
DATE: <u>11-14-1995</u>		INSPECTOR: <u>Linda Havelka</u>	
Insp. Type: <u>PR</u>	Insp. Status: <u>SI</u>	PA: Y N	Pass/Fail: P (F) Viol.: Y (N) NOV: Y (N)

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	<u>up</u>	
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)	<u>OK</u>	
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)	<u>OK</u>	
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous		

CORRECTIVE ACTION REQUIRED: Land owner complained of no production in three years wants wells removed - No production in over 2 years

Date Corrective Action Required By: _____ Date Remedied: MIT/PA letter sent 11/17/95

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.