

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/18/2024

Submitted Date:

03/18/2024

Document Number:

713300702

FIELD INSPECTION FORMLoc ID 332979 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Silver, Randy	720-827-6688	randy.silver@state.co.us	
, KPK	303-825-4822	cogcc@kpk.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242322	WELL	SI	05/01/2021	GW	123-10113	WATTENBERG HENRY E UT B 2	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Prime mover removed from pumping unit		
Corrective Action:	Comply with Rule 606	Date:	04/18/2024

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	safety guard		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	automation		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	pipd to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural Gas, REMOVED FROM PUMPING UNIT		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 242322 Type: WELL API Number: 123-10113 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Valves appeared to be closed at time of inspection

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/18/2024**BradenHead**Date of Last Brhd Test: 08/24/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary Inspector Michael Kester, conducted an on-site inspection. Location: Wattenburg Henry E UT B2 Operator: KPK API#: 123-10113 County: Weld While there, I observed well site with pumping unit, During this inspection, the following possible compliance issues were observed: Mechanical integrity Testing, Rule 417b, corrective action date 4-18-2024 Unused equipment, Rule 606, corrective action date 4-18-2024, photo 3 & 4</p> <p>Weather conditions: sunny and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection</p>	kesterm	03/18/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403723717	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6472325
713300703	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6472315