

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/15/2024

Submitted Date:

03/18/2024

Document Number:

713600833

FIELD INSPECTION FORMLoc ID 314203 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8005

Name of Operator: BERRY* WALTER V DBA BERRY ENERGY INC

Address: 1717 WASHINGTON AVE

City: GOLDEN State: CO Zip: 80401-

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Cruson, Michael		mgcruson@gmail.com	
Cruson, Michael	(303) 279-0190	mcruson@berryenergyinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228001	WELL	PA	12/28/2010	GW	099-06328	NEU 1-17	RI

General Comment:

This is a follow up of the previous reclamation inspections of the NEU #1-17 location.
 The corrective action of the previous inspection has not been completed.
 The location is not in compliance with the Final Reclamation requirements.
 See attached photos and additional details within this report.

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING

Comment

Corrective Action Date

1002b. SOIL REMOVAL AND
SEGREGATION

Comment

Corrective Action Date

1002c. PROTECTION OF SOILS

Comment

Corrective Action Date

1002E. SURFACE DISTRURBANCE MINIMIZATION

Comment

Corrective Action Date

1003a. Waste and Debris removed?

Comment

Corrective Action Date

Unused or unneeded equipment onsite?

Comment

Corrective Action Date

Pit, cellars, rat holes and other bores closed?

Comment

Corrective Action Date

Guy line anchors marked?

Comment

Corrective Action Date

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed **Fail** _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed **Fail** _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% **Fail** _____ Cropland: perennial forage _____

Weeds present **Fail** _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: **There is an abandoned pipe riser that remains at the location. The location has not been reclaimed and perennial desirable vegetation has not established. There are large areas approximately 200'x60' with undesirable weeds. The pipe riser must be removed and the location will need to be reseeded. Previous corrective action has not been performed. Corrective action needs to be performed immediately to obtain compliance.**

Corrective Action:	Comply with 1004 Rules	Date	
Overall Final Reclamation	Fail	Well Release on Active Location	<input type="checkbox"/>
		Multi-Well Location	<input type="checkbox"/>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403724126	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6472654
713600834	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6472637