

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/21/2024

Submitted Date:

03/21/2024

Document Number:

702403219

FIELD INSPECTION FORMLoc ID 318053 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240510	WELL	SI	06/01/2021	GW	123-08298	GUADAGNOLI 1	SI

General Comment:[This is a wellsite inspection.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Chainlink topped with barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	shares fencing with the WH.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panels & meter box.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities										
Facility ID:	240510	Type:	WELL	API Number:	123-08298	Status:	SI	Insp. Status:	SI	
Idle Well										
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:		SI since 5-2021 & last produced 4/2021. Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.								
Corrective Action:		Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.					Date:			04/21/2024
BradenHead										
Date of Last Brhd Test:		07/20/2023		Annual Brhd Completed?		Yes				
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:				
		End Surf Csg Pressure:		0						
Comment:		Plumbed to surface.								
Corrective Action:							Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Thursday 2-21-2024 at approximately 1500 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: This Field Inspection is due to a 901 order.</p> <p>Operator: KP Kauffman</p> <p>Location name:</p> <p>Location ID # 318053</p> <p>Well Name: Guadagnoli 1</p> <p>API # 05-123-08298</p> <p>County: Weld</p> <p>Weather: Sunny/Clear</p> <p>Location: Mostly dry.</p> <p>While there, I observed a wellsite, SI at the time of the inspection.</p> <p>During this inspection, I observed the following possible compliance issues:</p> <p>417.b MIT: Shut in wells, CA date 4-21-2024.</p> <p>See attached photos.</p> <p>A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p> <p>Any Corrective Actions from previous inspections not addressed are still applicable.</p>	revasr	03/21/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403728151	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6477221
702403220	location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6477210