

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/19/2024

Submitted Date:

03/21/2024

Document Number:

702502509

**FIELD INSPECTION FORM**Loc ID: 316335 Inspector Name: Burchett, Kirby On-Site Inspection: ☐ 2A Doc Num: **Operator Information:**

OGCC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS State: CO Zip: 80129

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Adams, Karen	(303) 886-8733	adams@kt-res.com	
Baumgras, Dan	(307) 321-3299	Dan@KT-Res.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266494	WELL	PR	08/01/2023	GW	103-10275	ANT HILL UNIT RBC WG 31-42	PR

**General Comment:****ECMC Inspection Report Summary**

On Tuesday, 03/19/2024, Inspector Kirby Burchett, conducted a follow up field inspection at KT Resources LLC on the Ant Hill Unit RBC WG 31-42 well, Location #316335, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District, Black Bear and High Priority area with NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #702501153 on 6/13/23 and Insp. #698100303 on 10/24/24. All Corrective Actions have not been resolved and original due dates will remain:

1. API Number not displayed on tank battery sign. (Resolved)
2. Gas meter calibration card not visibly displayed. (Resolved)
3. Stormwater BMP's need implementation and maintenance. (Unresolved)
4. Unused equipment. (Resolved)
5. Chemical tank labels illegible. (Resolved)

Refer to Inspection Photos for observed compliance issues.

While there during normal operations the following additional compliance issues were observed:

1. Gas calibration out of compliance.
2. Relief riser missing rain cap.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	As Wellhead signs are replaced: The Well name; The API Number; and Its legal location, including the quarter/quarter section will be required.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: (800) 288-0560 or 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heater Treater	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	#		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Chemical tank on containment	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other				
Comment:	Unlined earth and metal			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Inadequate			
Comment:	Unlined earth and metal. Inspection #698100303 on 10/24/23 indicated berm was too small to contain 150% tank capacity of the largest tank.			
Corrective Action:	Repair or install berms or other secondary containment devices.			Date: 11/24/2023



Inspected Facilities									
Facility ID:	266494	Type:	WELL	API Number:	103-10275	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	January 2024 Production Report								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Culverts				
				Material Handling And Spill Prevention		
Ditches						

Comment: Stormwater BMPs need implementation and maintenance.

Corrective Action: Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 04/28/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403727510	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6476538">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6476538</a>
702502510	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6476531">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6476531</a>