

BILL BARRETT CORPORATION E-BILL

Kaufman 21D-24-692 MAMM CREEK Garfield County , Colorado

Cement Surface Casing
10-Aug-2011

Post Job Report

SUMMIT Version: 7.20.130 Wednesday, August 10, 2011 09:22:00

Summit Version: 7.20.130

Cementing Job Summary

The Road to Excellence Starts with Safety

Sold To #: 3	1210	2		Ship To			o Excelle		uote		Saie	L y		9.	ales O	rdor	. #. 0	22010	10
											on: H	ondo	rcon			uei	#. (3040	40
Customer: BILL BARRETT CORPORATION E-BILL Customer Rep: Henderson, Josh Well Name: Kaufman Well #: 21D-24-692 API/UWI #: 05-045-19915																			
	Field: MAMM CREEK City (SAP): SILT County/Parish: Garfield State: Colorado																		
												doa	OD !					0.02	2 0000
Lat: N 39.51 Contractor:							orm Na					ueg.	UK	VV - IU	o deg	. 23	min.	0.93	3 secs.
						g/Platt	orm Na	me/Nu	um: H	ProPe	etro								
Job Purpos				Casing			. 0	0		0									
Well Type:		•					e: Ceme									00.44			
Sales Perso	n: M	EILI,	MARSI	HALL	Sr	vc Sup	perviso				HAL	_ M	BU II) Emp	p#: 3	394	39		
								Perso											
HES Emp			xp Hrs				Emp Nar		Exp		Emp#				Nam	е		Hrs	Emp #
BORSZICH STEPHEN A			6	412388		AGERS erard	, MICHA	LL	6	3	39439	S	SINCL	AIR, D	AN J		6		338784
WILKERSO	N, JAN	/IES	6	496763															
Michael																			
	15.		-					quipm			5.			1 -		• • •	- ·		
HES Unit #		nce-1 v		HES Un					HES U		Dista		way		IES Ur				1 way
10001431	120			1072464	3	120 mil	е	10	08294	69	120	mile		10)87242	9	12	0 mile	!
11360883	120	mile																	
								ob Ho											
Date	On Lo Hours	ocation S		perating Hours	Date		On Lo Hours	ocation s		perati ours	ng		Dat		On Lo Hours	catio	n		erating Hours
08/10/2011		6		1															
TOTAL			•				,	Tota	al is th	ne sun	n of ea	ch co	lumn .	separa	ately				
				Job										Job	Times	;			
Formation Na	ame													Date		Tir	ne	Tir	ne Zone
Formation De	epth (I	MD) T	ор			Botto	m			alled (10 - A	ug - 2	2011	11:	:00		MST
Form Type				ВН						n Loc				ug - 2		15	:00		MST
Job depth MI	D		800. ft			h TVD		800. ft		ob Sta					- 2011 19:4				MST
Water Depth				Wk	Ht Ak	ove FI	oor	1. ft			mplete		10 - A	ug - 2	2011	20	:49		MST
Perforation D	epth ((MD)	rom			То				eparte	ed Loc	;							
5		N		0:	.	in.		Well D				_							D 44
Description		New / Used	Ma: press	ure in	-	ID in	Weight Ibm/ft		Thre	ead		Gra	ide	Top I		Botto MD ft		Top TVD ft	Bottom TVD ft
12 1/4" Open			psi	9	1	2.25										820	-	11	11
Hole 9 5/8" Surfac	e	New		9.62	25 8	.921	36.					J-5	55			796.	4		
Casing																			
							les/Ren	tal/3 rd	Party	y (HE	S)		,						
					riptio	n						Qty	Qty		Dept	h		Supp	lier
PLUG,CMTG,	TOP,9	5/8,H	WE,8.16	MIN/9.0	6 MA							1	E	Α					
							Tools a	nd Ac	cess	ories									
Type	Size	Qty	Make			/pe	Size	Qty	Ma	ke [Depth		Тур	е	Siz		(Qty	Make
Guide Shoe					Packe								Plug		9.6	25		1	HES
Float Shoe						e Plug							om P						
Float Collar					Retair	ner							plug				014		
Insert Float														tainer	9.6	2 5	51/	/AGE	
Stage Tool							/iccalla	nacus	N/ot	oriolo		cen	tralize	ers					
Gelling Agt			Со	nc		Surfac	/liscella	neous	o ivial	Conc	_	Δci	d Typ	Δ		Qt	v	1	Conc %
Treatment Fl	d		Co			Inhibito				Conc		San	d Typ	e e		Siz			Qty 76
. roadinelit Fl	u		CU			אוטוווווו	J1			Conc		Juan	ישייטן.	, .		JUI.			× · y

Summit Version: 7.20.130

Cementing Job Summary

	Fluid Data													
S	Stage/Plug #: 1													
Fluid	Stage 1	Гуре		Fluid N	lame		Qty	Qty	Mixing		Mix Fluid			al Mix
#								uom	Density Ibm/gal	ft3/sk	Gal/sk	bbl/min	Fluid	Gal/sk
1	Water Sp	acer					20.00	bbl		.0	.0	.0		
2	VersaCer	n Lead	VER	SACEM (TM) SY	STEM (4520	10)	120.0	sacks	12.3	2.38	13.77		13	3.77
	Cement													
	13.77 Gal		FRE	SH WATER										
3	SwiftCem	n Tail	SWI	FTCEM (TM) SYS	STEM (45299	90)	120.0	sacks	14.2	1.43	6.85		6	.85
	Cement													
	6.85 Gal		FRE	SH WATER										
4	Displace	ment					59.00	bbl		.0	0.	.0		
C	alculated	Values	3	Pressu	res				V	olumes				
Displa	cement	58.9	9	Shut In: Instant		Lost Re	eturns	0	Cement S	lurry	81.5	Pad		
Top O	f Cement	SURFA	ACE :	5 Min		Cemen	t Returns	10	Actual Di	isplaceme	ent 58.8	Treatm	nent	
Frac G	Fradient		1	15 Min		Spacer	S	20	Load and	Breakdov	vn	Total J	lob	160
Rates														
Circula	ating NO	NE		Mixing	5		Displacement		5/2		Avg. Job		5	5
Cemei	nt Left In Pi	ре	Amo	ount 43.22 ft Re	ason Sho e	Joint								
Frac R	Ring # 1 @	1	D	Frac ring # 2	@ //)	Frac Ring	g#3@	ID	F	rac Ring#	4 @	IE)
The I	The Information Stated Herein Is Correct Customer Representative Signature													

Cementing Job Log

The Road to Excellence Starts with Safety

 Sold To #: 343492
 Ship To #: 2871050
 Quote #:
 Sales Order #: 8384048

Customer: BILL BARRETT CORPORATION E-BILL Customer Rep: Henderson, Josh

Well Name: Kaufman Well #: 21D-24-692 API/UWI #: 05-045-19915

Field: MAMM CREEK City (SAP): SILT County/Parish: Garfield State: Colorado

Legal Description:

Lat: N 39.516 deg. OR N 39 deg. 30 min. 57.845 secs. **Long:** W 107.614 deg. OR W -108 deg. 23 min. 8.938 secs.

Contractor: ProPetro Services Inc. Rig/Platform Name/Num: ProPetro

Job Purpose: Cement Surface Casing Ticket Amount:

Well Type: Development Well Job Type: Cement Surface Casing

Sales Person: METLI, MARSHALL Srvc Supervisor: MAGERS, MICHAEL MBU ID Emp #: 339439

Sales Person: METLI, MARSH	IALL Srvc S	upervi	sor: MA	<u>GERS, M</u>	ICHAEL	MBUIL) Emp #:	339439	
Activity Description	Date/Time	Cht	Rate bbl/ min	Volume bbl		Pressure psig		Comments	
		#		Stage	Total	Tubing	Casing		
Crew Leave Yard	08/10/2011 13:00							HES ALL PRESENT	
Arrive At Loc	08/10/2011 15:00							RIG WAS STILL DRILLING WHEN HES ARRIVED	
Assessment Of Location	08/10/2011							GOOD CONDITION	
Safety Meeting	15:10								
Pre-Rig Up Safety Meeting	08/10/2011 15:20							1 PICKUP 1 ELITE 1 BULK TRUCK	
Rig-Up Equipment	08/10/2011 15:30							TD-800 TP-790.9 SJ- 43.22 MW-8.33 CSG- 9.625 36# J-55 OH- 12.75"	
Safety Huddle	08/10/2011 19:40							RIG CREW AND HES ALL PRESENT	
Start Job	08/10/2011 19:48								
Other	08/10/2011 19:49		2	2			15.0	FILL LINES	
Pressure Test	08/10/2011 19:51		0.5	0.5			5052. 0	PSI TEST OK	
Pump Spacer 1	08/10/2011 19:57		3	20			59.0	FRESH WATER	
Pump Lead Cement	08/10/2011 20:03		5	50.9			166.0	VERSACEM 120 SKS 12.3 PPG 2.38 FT3/SK 13.77 GAL/SK	
Pump Tail Cement	08/10/2011 20:13		5	30.6			195.0	SWIFTCEM 120 SKS 14.2 PPG 1.43 FT3/SK 6.85 GAL/SK GOT RETURNS AT 22 BBLS GONE	
Shutdown	08/10/2011 20:19								
Drop Plug	08/10/2011 20:29							PLUG AWAY NO PROBLEMS	

Sold To #: 343492 Ship To #:2871050 Quote #: Sales Order #: 8384048

SUMMIT Version: 7.20.130 Wednesday, August 10, 2011 09:22:00



Cementing Job Log


Activity Description	Date/Time	Cht	Rate bbl/ min	Volume bbl			Pressure psig Comme	
		#		Stage	Total	Tubing	Casing	
Pump Displacement	08/10/2011 20:30		5	58.8			213.0	FRESH WATER GOT RETURNS BACK AT 9 BBLS INTO DISPLACEMENT
Slow Rate	08/10/2011 20:39		2	49			219.0	GOT 10 BBLS OF CEMENT TO SURFACE
Bump Plug	08/10/2011 20:43		2	58.8			245.0	BUMPED PLUG
Check Floats	08/10/2011 20:45			58.8			780.0	FLOATS HELD/GOT 1/2BBL BACK INTO DISPLACEMENT
Shut In Well	08/10/2011 20:47						195.0	SHUT IN 2" LO-TORC VALUE WITH 195 PSI
Release Casing Pressure	08/10/2011 20:48							RELEASED PRESSURE
End Job	08/10/2011 20:49							THANKS FOR USING HES AND THE CREW OF MIKE MAGERS

Sold To #: 343492 Ship To #:2871050 Quote #: Sales Order #: 8384048

SUMMIT Version: 7.20.130 Wednesday, August 10, 2011 09:22:00

BILL BARRETT PRO PETRO

9.625 SURFACE



Customer: BILL BARRETT PRO PETRO
Well Description: KAUFMAN 21D-24-692
Company Rep: JOSH HENDERSON

Job Date: 10-Aug-2011
Job Type: SURFACE
Cement Supervisor: MIKE MAGERS


Sales Order #: 8384048 ADC Used: YES

Elite #: 7 DAN SINCLAIR

OptiCem v6.3.4 10-Aug-11 21:02

BILL BARRETT PRO PETRO

9.625 SURFACE



EVENT #	EVENT	VOLUME	SACKS	WEIGHT	YIELD	GAL/ SK
1	Start Job					
6	Test Lines	5000.0				
9	H2O Spacer	20.0	3 bbls/min			
13	Pump Lead Cement	50.9	120	12.3	2.38	13.77
15	Pump Tail Cement	30.6	120	14.2	1.43	6.85
48	Shut Down					
32	Drop Plug					
23	Pump Frsh Wtr Displacement	58.8	5 bbls/min			
1085	Slow Rate	49.0	2 bbls/min			
26	Bump Plug	189 PSI	Plus	500	Over	689 PSI
511	Check Floats					
2	Release Psi / Job Over	0.0				
			Dol	Vot Ove	raisoi	ace
DISPLACEMENT	TOTAL PIPE	SHOE JOINT L	.ENGTH	FLOAT COLLAR	BBL/FT	H2O REQ.
58.84	790.9	43.20		747.70	0.0787	160
PSI to Lift Pipe	341	******!!-	o Mud Ca	oloo on For	h Tior**	***
Total Displacement	58.84	******Use Mud Scales on Each Tier*****				
CALCULATI	ED DIFFERENTIAL PSI	189		TOTAL FLUID	160	
Collapse	1400	BURST	2	370	SO#	8384048

CUSTOMER SURVEY

Sales Order #: Line Item: Survey Conducted Date:

8384048 10 8/10/2011

Customer: Job Type (BOM):

BILL BARRETT CORPORATION E-BILL

CMT SURFACE CASING BOM

Customer Representative:

API / UWI: (leave blank if unknown)

JOSH HENDERSON 05-045-19915

Well Name:Well Number:Kaufman21D-24-692

Well Type: Well Country:

Development Well United States of America

H2S Present:Well State:Well County:NoColoradoGarfield

Dear Customer,

We hope that you were satisfied with the service quality of this job performed by Halliburton. It is the aim of our management and service personnel to deliver equipment and service of a standard unmatched in the service sector of the energy industry.

Please take the time to let us know if our performance met with your satisfaction. Please be as critical as possible to ensure we constantly improve our service. Your comments are of great value to us and are intended for the exclusive use of Halliburton.

CUSTOMER SATISFACTION SURVEY

CATEGORY	CUSTOMER SATISFACTION RESPONSE	
Survey Conducted Date	The date the survey was conducted	8/10/2011
Survey Interviewer	The survey interviewer is the person who initiated the survey.	MICHAEL MAGERS (HX13672)
Customer Participation	Did the customer partipcipate in this survey? (Y/N)	Yes
Customer Representative	Enter the Customer representative name	JOSH HENDERSON
HSE	Was our HSE performance satisfactory? Circle Y or N	Yes
Equipment	Were you satisfied with our Equipment? Circle Y or N	Yes
Personnel	Were you satisfied with our people? Circle Y or N	Yes
Customer Comment	Customer's Comment	
Job DVA	Did we provide job DVA above our normal service today? Circle Y or N	No
Time	Please enter hours in decimal format to nearest quarter hour.	
Other	Enter short text for other efficiencies gained.	
Customer Initials	Customer's Initials	
Please provide details	Please describe how the job efficiencies were gained.	

CUSTOMER SIGNATURE

 KPI Number:
 HBCK66020110808150700K301
 Page 1 of 3

 EJCS Number:
 HBCK66020110808150700E301
 8/10/2011

CUSTOMER SURVEY

Sales Order #:	Line Item:	Survey Conducted Date:
Sales Order #:	Line item:	Survey Conducted Date:

8384048 10 8/10/2011

Customer: Job Type (BOM):

BILL BARRETT CORPORATION E-BILL

CMT SURFACE CASING BOM

Customer Representative:

API / UWI: (leave blank if unknown)

Customer Representative:API / UWI: (leave blank if unknown)JOSH HENDERSON05-045-19915

Well Name:Well Number:Kaufman21D-24-692

Well Type: Well Country:

Development Well United States of America

H2S Present:Well State:Well County:NoColoradoGarfield

KEY PERFORMANCE INDICATORS

General						
Survey Conducted Date	8/10/2011					
The date the survey was conducted						

Cementing KPI Survey	
Type of Job	0
Select the type of job. (Cementing or Non-Cementing)	
Select the Maximum Deviation range for this Job	Vertical
What is the highest deviation for the job you just completed? This may not be the maximum well deviation.	
Total Operating Time (hours)	2
Total Operating Hours Including Rig-up, Pumping, Rig-down. Enter in decimal format.	
HSE Incident, Accident, Injury	No
HSE Incident, Accident, Injury. This should be recordable incidents only.	
Was the job purpose achieved?	Yes
Was the job delivered correctly as per customer agreed design?	
Operating Hours (Pumping Hours)	1
Total number of hours pumping fluid on this job. Enter in decimal format.	
Customer Non-Productive Rig Time (hrs)	0
Lost time due to Halliburton in the start, execution, or completion of an ordered service or product, or delays in a follow-on service. Enter in decimal format. 0 if none.	
Type of Rig Classification Job Was Performed	Workover
Type Of Rig (classification) Job Was Performed On	
Number Of JSAs Performed	4
Number Of Jsas Performed	
Number of Unplanned Shutdowns	0
Unplanned shutdown is when injection stops for any period of time.	
Was this a Primary Cement Job (Yes / No)	Yes

KPI Number: HBCK66020110808150700K301

EJCS Number: HBCK66020110808150700E301 8/10/2011

Page 2 of 3

CUSTOMER SURVEY

Sales Order #: Survey Conducted Date:

8384048 10 8/10/2011

Customer: Job Type (BOM):

BILL BARRETT CORPORATION E-BILL CMT SURFACE CASING BOM

Customer Representative: API / UWI: (leave blank if unknown)

JOSH HENDERSON 05-045-19915
Well Name: Well Number:

Kaufman 21D-24-692

Well Type: Well Country:

Development Well United States of America

H2S Present:Well State:Well County:NoColoradoGarfield

Primary Cement Job= Casing job, Liner job, or Tie-back job.	
Did We Run Wiper Plugs?	Тор
Did We Run Top And Bottom Casing Wiper Plugs?	
Mixing Density of Job Stayed in Designed Density Range (0-100%)	95
Density Range defined as +/20 ppg. Calculation: Total BBLs cment mixed at designed density divided by total BBLs of cement multiplied by 100	
Was Automated Density Control Used?	Yes
Was Automated Density Control (ADC) Used ?	
Pump Rate (percent) of Job Stayed At Designed Pump Rate	95
Pump Rate range defined as +/- 1bbl/min. Calculation: Total BBLs of fluid pumped at the designed rate divided by Total BBLs of fluid pumped, multiplied by 100	
Nbr of Remedial Sqz Jobs Rqd - Competition	0
Number Of Remedial Squeeze Jobs Required After Primary Job Performed By Competition	
Nbr of Remedial Plug Jobs Rqd - HES	0
Number Of Remedial Plug Jobs Needed After Primary Plug Pumped By HES	
Nbr of Remedial Sqz Jobs Rqd - HES	0
Number Of Remedial Squeeze Jobs Required After Primary Job Performed By HES	

 KPI Number:
 HBCK66020110808150700K301
 Page 3 of 3

 EJCS Number:
 HBCK66020110808150700E301
 8/10/2011