
From: Todd Hutson [mailto:thutson@qrinc.com]
Sent: Friday, October 21, 2011 2:43 PM
To: Fischer, Alex
Cc: Eckman, Annie
Subject: RE: Pits

For Facility 272982

Thanks, Todd

R. Todd Hutson
thutson@qrinc.com
Environmental Manager
Quicksilver Resources Inc.

801 Cherry Street
Suite 3700, Unit 19
Fort Worth, Texas 76102
direct: 817-665-5434
mobile: 817-422-2883

From: Fischer, Alex [mailto:Alex.Fischer@state.co.us]
Sent: Thursday, October 20, 2011 11:43 AM
To: Todd Hutson
Cc: Eckman, Annie
Subject: RE: Pits

Todd,

For the Walker 12-5, Facility ID 286608.

Provide a Form 27 with diagram showing the four pits and locations:

**Facility number 286608 authorizes the four lined pits that you see on your image.
Locations are as follows:**

**152' X 152' – 40.576975, -107.782028
173' X 173' – 40.576522, -107.782952
206' X 206' – 40.576006, -107.783900
786' X 330' – 40.578056, -107.778133**

For the Walker 12-5 Flare Pit, facility ID 272982:
**Provide a Form 27 with the following locations.
The last pit is located as follows:**

40.576053, -107.778758

For the pit that was permitted and never constructed:

Provide a Form 27 explaining things. We will then do a visual inspection.

I believe that this should clean this part up.

Thanks
Alex

From: Todd Hutson [mailto:thutson@qrinc.com]
Sent: Thursday, October 20, 2011 10:16 AM
To: Fischer, Alex
Subject: Pits

Alex,

I was supposed to submit you a form 27 for one of those pits but I can't remember

which one and for what purpose. Can you please jog my memory?

Thanks, Todd

R. Todd Hutson

thutson@qrinc.com

Environmental Manager

Quicksilver Resources Inc.

801 Cherry Street

Suite 3700, Unit 19

Fort Worth, Texas 76102

direct: 817-665-5434

mobile: 817-422-2883