

Well:	SHIDELER 19-14D
Pad:	O19EB
API No:	05-045-21832
Permit No:	

### **Bradenhead Pressure Report Following Primary Cement Job**

Date Cemented:	03/06/2013
Plug Bumped:	Yes

Annular Fluid Level After Job (Static or Falling?):	Yes	
If falling, barrels of mud added until stabilized:	N/A	barrels

WOC Time:	6 hrs
Bond Log Run:	Temp log in lieu of CBL

Casing Slips Set:	Yes
-------------------	-----

### **Bradenhead Pressures**

6 hrs:	0	psig
12 hrs:	0	psig
24 hrs:	0	psig
48 hrs:	0	psig
72 hrs:	0	psig

### **Comments**

This well lost returns while pumping displacement during the primary cement job. The plug bumped and the floats held. Bradenhead pressure was monitored until a CBL could be performed. Bradenhead pressure has remained at 0 psi to date.