

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

Comments

Thank you for choosing Nabors

Database File: nblpekerred&t234.db
Dataset Pathname: pass1
Presentation Format: ctd_dm
Dataset Creation: Fri May 23 09:20:29 2014 by Log Std Casedhole 10081
Charted by: Depth in Feet scaled 1:240

400 TRAVEL TIME (usec) 200
10 Collar Locator -2
0 Gamma Ray (GAPI) 200

0 AMP3 (mV) 100 200 VDL 1200
0 Amplified Amp 3 (mV) 10

400 TRAVEL TIME (usec) 200
10 Collar Locator -2
0 Gamma Ray (GAPI) 200

0 AMP3 (mV) 100 200 VDL 1200
0 Amplified Amp 3 (mV) 10