

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES

Inspection Date:
10/01/2014Document Number:
667200555Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	226433	313856	SCHURE, KYM	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 18600Name of Operator: COLORADO INTERSTATE GAS COMPANY LLCAddress: P O BOX 1087City: COLORADO State: CO Zip: 80944

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Lively, Kevin	970-867-4243	kevin_lively@kindermorgan.com	

Compliance Summary:QtrQtr: NWSW Sec: 30 Twp: 3N Range: 57W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/01/2014	667200068	AC	SI	SATISFACTORY			No
10/08/2013	664001325	AC	SI	SATISFACTORY			No
05/06/2013	664000945	AC	AC	SATISFACTORY			No
10/31/2012	663300714	AC	AC	SATISFACTORY	P		No
04/25/2012	663400189	AC	SI	SATISFACTORY			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
226433	WELL	AC	05/11/1971	STOW	087-07169	FORT MORGAN UNIT 23	AC	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Inspector Name: SCHURE, KYM

<u>Signs/Marker:</u>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V):	SATISFACTORY	Corrective Date:	
Comment:			
Corrective Action:			

<u>Spills:</u>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<u>Fencing/:</u>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD				

<u>Equipment:</u>					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Horizontal Separator	1	SATISFACTORY			

<u>Venting:</u>		
Yes/No	Comment	

<u>Flaring:</u>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 226433

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 226433 Type: WELL API Number: 087-07169 Status: AC Insp. Status: AC

BradenHead

Comment: No problems found

CA: _____

CA Date: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Inspector Name: SCHURE, KYM

Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
<u>Water Well:</u>			
DWR Receipt Num: _____		Owner Name: _____	GPS : _____
<u>Field Parameters:</u>			
Sample Location: _____			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____		Wildlife Protection Devices (fired vessels): _____	
Reclamation - Storm Water - Pit			
<u>Interim Reclamation:</u>			
Date Interim Reclamation Started: _____		Date Interim Reclamation Completed: _____	
Land Use: _____			
Comment: _____			
1003a.	Debris removed? _____ CM _____		
	CA _____	CA Date _____	
	Waste Material Onsite? _____ CM _____		
	CA _____	CA Date _____	
	Unused or unneeded equipment onsite? _____ CM _____		
	CA _____	CA Date _____	
	Pit, cellars, rat holes and other bores closed? _____ CM _____		
	CA _____	CA Date _____	
	Guy line anchors removed? _____ CM _____		
	CA _____	CA Date _____	
	Guy line anchors marked? _____ CM _____		
	CA _____	CA Date _____	
1003b.	Area no longer in use? _____		Production areas stabilized ? _____
1003c.	Compacted areas have been cross ripped? _____		
1003d.	Drilling pit closed? _____		Subsidence over on drill pit? _____
	Cuttings management: _____		
1003e.	Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____		
	Production areas have been stabilized? _____		Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION			
<u>Cropland</u>			
	Top soil replaced _____	Recontoured _____	Perennial forage re-established _____
<u>Non-Cropland</u>			

Inspector Name: SCHURE, KYM

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

S/A/V: SATISFACTOR
Y _____

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT