



photo 1: Well sign. MacGregor 32-25



photo 2: Facing west along the access road towards the location off of the main road.



photo 3: Facing east back towards the main road. It appears sediment is being transported down towards the main access road.



photo 4: Facing southwest towards the location.



photo 5: Facing southwest towards the location.



photo 6: The northeast deadman is not marked.