



Photo 1. View of stormwater erosion channel forming in southwestern portion of the project area. Channel is approximately 12 inches wide and deep.





Photo 2. View of the western portion of the project area from the southwestern corner facing northward. Revegetation is comprised of grasses such as crested wheatgrass (*Agropyron cristatum*) and intermediate wheatgrass (*Thinopyron intermedium*) as well as weedy cheatgrass (*Bromus tectorum*).



Photo 3. View of the project area from the northeastern corner facing center.





Photo 4. View of the eastern portion of the project area from the northeastern corner facing southward. Although much of this area is covered with snow, it appears that there is little vegetation in this area and it needs to be monitored and re-seeded if necessary.