

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/08/2016

Document Number:

666802540

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	271591	335351	Murray, Richard	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Compliance Summary:**QtrQtr: SWSW Sec: 27 Twp: 6S Range: 93W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/28/2011	200300466	PR	PR	SATISFACTORY			No
02/14/2011	200296402	PR	PR	SATISFACTORY			No
03/28/2007	200108144	PR	PR	SATISFACTORY	In Process	Pass	No
06/19/2006	200098707	PR	PR	SATISFACTORY	In Process	Pass	No
06/16/2006	200097787	CO	PR	SATISFACTORY		Pass	No
05/16/2006	200096718	PR	PR	SATISFACTORY	In Process	Pass	No
10/27/2005	200085057	PR	PR	SATISFACTORY		Pass	No
06/14/2004	200061540	CC	DG	SATISFACTORY		Pass	No

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
271591	WELL	PR	11/22/2004	GW	045-09903	GMR 28-10D (M27NW)	PR	<input checked="" type="checkbox"/>
271592	WELL	PR	11/28/2005	GW	045-09904	GMR 27-12D(M27NW)	PR	<input checked="" type="checkbox"/>
271608	WELL	PR	11/25/2004	GW	045-09906	GMR 27-13D(M27NW)	PR	<input checked="" type="checkbox"/>
271698	WELL	PR	11/21/2005	GW	045-09935	GMR 28-9D (M27NW)	PR	<input checked="" type="checkbox"/>
271761	WELL	PR	11/24/2004	GW	045-09947	GMR 28-16D(M27NW)	PR	<input checked="" type="checkbox"/>

Inspector Name: Murray, Richard

272099	WELL	PR	11/19/2004	GW	045-10024	GMR 28-8D (M27NW)	PR	✗
295484	WELL	PR	03/18/2009	GW	045-15773	GMR 27-13A (M27NW)	PR	✗
295485	WELL	PR	04/29/2009	GW	045-15774	GMR 27-14A(M27NW)	PR	✗
295488	WELL	PR	04/19/2009	GW	045-15775	GMR 27-11D (M27NW)	PR	✗
295489	WELL	PR	04/29/2009	GW	045-15776	GMR 27-12A(M27NW)	PR	✗
296343	WELL	PR	04/16/2009	GW	045-15993	GMR 27-13B (M27NW)	PR	✗
296344	WELL	PR	04/16/2009	GW	045-15994	GMR 27-12B (M27NW)	PR	✗

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Equipment:**

Type: Emission Control Device	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action	Date:		
Type: Horizontal Heated Separator	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action	Date:		
Type: Ancillary equipment	# 2	Satisfactory/Action Required:	SATISFACTORY
Comment	Blow down muffler, Chemical unit at wellhead		
Corrective Action	Date:		
Type: Vertical Heated Separator	# 11	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action	Date:		

Inspector Name: Murray, Richard

Type: Gas Meter Run	# 1	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action		Date:

**Tanks and Berms:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
METHANOL	1	1000 GAL	STEEL AST	,

S/AR	SATISFACTORY	Comment:	Centralized battery
Corrective Action:		Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action		Corrective Date	
Comment			

**Tanks and Berms:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CONDENSATE	2	500 BBLS	STEEL AST	39.493140,-107.767990

S/AR	SATISFACTORY	Comment:	
Corrective Action:		Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
Comment			

**Venting:**

Yes/No	NO
Comment	

**Flaring:**

Type		Satisfactory/Action Required	
Comment:			

Inspector Name: Murray, Richard

Corrective Action:

Correct Action  
Date:

### **Predrill**

Location ID: 271591

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

CDP Num.: \_\_\_\_\_

### **Form 2A COAs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

### **Wildlife BMPs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Comment:** \_\_\_\_\_

### **Staking:**

### **On Site Inspection (305):**

#### **Surface Owner Contact Information:**

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

#### **Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

#### **LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

#### **Summary of Landowner Issues:**

\_\_\_\_\_

#### **Summary of Operator Response to Landowner Issues:**

\_\_\_\_\_

#### **Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**

\_\_\_\_\_

### **Facility**

Facility ID: 271591 Type: WELL API Number: 045-09903 Status: PR Insp. Status: PR

#### **Producing Well**

Comment: Plunger lift

Facility ID: 271592 Type: WELL API Number: 045-09904 Status: PR Insp. Status: PR

#### **Producing Well**

Comment: Plunger lift

Facility ID: 271608 Type: WELL API Number: 045-09906 Status: PR Insp. Status: PR

Inspector Name: Murray, Richard

**Producing Well**

Comment: **Plunger lift**

Facility ID: 271698 Type: WELL API Number: 045-09935 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 271761 Type: WELL API Number: 045-09947 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 272099 Type: WELL API Number: 045-10024 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 295484 Type: WELL API Number: 045-15773 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 295485 Type: WELL API Number: 045-15774 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 295488 Type: WELL API Number: 045-15775 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 295489 Type: WELL API Number: 045-15776 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 296343 Type: WELL API Number: 045-15993 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 296344 Type: WELL API Number: 045-15994 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

**Environmental**

**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Inspector Name: Murray, Richard

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): Y \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: ON \_\_\_\_\_ Wildlife Protection Devices (fired vessels): YES \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? Pass \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Inspector Name: Murray, Richard

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_

Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Culverts	Pass			
		Gravel	Pass			
Retention Ponds	Pass					
		Ditches	Pass			
Seeding	Pass					
Berms	Pass					

S/A/V: SATISFACTORY \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT