

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/03/2016

Submitted Date:

10/03/2016

Document Number:

680702842**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 327620      Peterson, Tom      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER      State: CO      Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email                                  | Comment |
|--------------|-------|--|---------|
| ,            |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name         | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 247137      | WELL | PR     | 04/08/1992  | GW         | 123-14934 | BLAKE FEDERAL 14-12 2 | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |                                   |       |  |
|--------------------|-----------------------------------|-------|--|
| <b>Fencing/:</b>   |                                   |       |  |
| Type               | SEPARATOR                         |       |  |
| Comment:           | <a href="#">Livestock fencing</a> |       |  |
| Corrective Action: |                                   | Date: |  |
| Type               | TANK BATTERY                      |       |  |
| Comment:           | <a href="#">Livestock fencing</a> |       |  |
| Corrective Action: |                                   | Date: |  |
| Type               | WELLHEAD                          |       |  |
| Comment:           | <a href="#">Panel</a>             |       |  |
| Corrective Action: |                                   | Date: |  |

|                                   |                                       |       |                 |
|-----------------------------------|---------------------------------------|-------|-----------------|
| <b>Equipment:</b>                 |                                       |       | corrective date |
| Type: Pig Station                 | # 1                                   |       |                 |
| Comment:                          | <a href="#">N40.32140 W-104.73245</a> |       |                 |
| Corrective Action:                |                                       | Date: |                 |
| Type: Gas Meter Run               | # 1                                   |       |                 |
| Comment:                          |                                       |       |                 |
| Corrective Action:                |                                       | Date: |                 |
| Type: Horizontal Heated Separator | # 1                                   |       |                 |

|  |     |       |
|--|-----|-------|
| Comment: <a href="#">N40.32140 W-104.73257</a> |     | Date: |
| Corrective Action:                             |     | Date: |
| Type: Ancillary equipment                      | # 1 |       |
| Comment: <a href="#">Automation array</a>      |     | Date: |
| Corrective Action:                             |     | Date: |
| Type: Plunger Lift                             | # 1 |       |
| Comment:                                       |     | Date: |
| Corrective Action:                             |     | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tanak ID | SE GPS                |
|--------------------|---|----------|-----------|----------|-----------------------|
| CRUDE OIL          | 1 | 300 BBLS | STEEL AST |          | 40.321120,-104.732750 |
| Comment:           |   |          |           |          |                       |
| Corrective Action: |   |          |           |          | Date:                 |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type           | Tanak ID | SE GPS                |
|--------------------|---|----------|----------------|----------|-----------------------|
| PRODUCED WATER     | 1 | 100 BBLS | PBV FIBERGLASS |          | 40.321120,-104.732750 |
| Comment:           |   |          |                |          |                       |
| Corrective Action: |   |          |                |          | Date:                 |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|        |    |
|--------|----|
| Yes/No | NO |
|--------|----|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|--|--|--|--|

| Inspected Facilities |        |                                   |      |             |           |         |    |               |    |
|----------------------|--------|-----------------------------------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 247137 | Type:                             | WELL | API Number: | 123-14934 | Status: | PR | Insp. Status: | PR |
| Producing Well       |        |                                   |      |             |           |         |    |               |    |
| Comment:             |        | PR                                |      |             |           |         |    |               |    |
| Corrective Action:   |        |                                   |      |             |           |         |    | Date:         |    |
| BradenHead           |        |                                   |      |             |           |         |    |               |    |
| Comment:             |        | Bradenhead is exposed at surface. |      |             |           |         |    |               |    |
| Corrective Action:   |        |                                   |      |             |           |         |    | Date:         |    |

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed?  P 

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite?  Pass 

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed?  Pass 

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐



**Storm Water:**

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date:

**Pits:** ☒ NO SURFACE INDICATION OF PIT