



Photo#1: Overview of Location to South from Interim Reclamation Area.

January 12, 2017

Inspection Photos: TEP Loc#433948 Puckett GM



Photo#2: Sediment trap at NE Corner of Pad

January 12, 2017

Inspection Photos: TEP Loc#433948 Puckett GM



Photo#3: Last year's heavy growth of Annual Weeds in Interim Rec Area,

Inspection Photos: TEP Loc#433948 Puckett GM

January 12, 2017



Photo#4: View of Rock Wall and Gravel Berm at East Edge of Location

Inspection Photos: TEP Loc#433948 Puckett GM

January 12, 2017