



photo 1: Well sign at the location.



photo 2: Facing toward the production equipment.



**photo 3:** The sound walls have fallen over.



**photo 4:** Facing along the east side of the location.