



1
2
3-
4
1
8
2
4

view from 40.122798, -104.673418 to northwest with 123-41824 identified, temporary storage tanks inside lined and bermed area to left of wells, temporary pipes connecting wells to tanks running in line along ground directly below wells

2.15.2017 14:19