



view to east from edge of bermed storage area
Areas to north and south of pipes connecting wells to
storage tanks have been scraped with soils removed
for disposal

2.15.2017 14:23