

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/07/2017

Submitted Date:

03/23/2017

Document Number:

672500413**FIELD INSPECTION FORM**

Loc ID 305447 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 370 17TH STREET #2170City: DENVER State: CO Zip: 80202**Status Summary:**☒ THIS IS A FOLLOW UP INSPECTION☐ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		Cogcc.inspections@crestonepr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434333	WELL	DG	10/17/2016	LO	123-38104	Woolley Sosa 2A-7H-E168	DG
434334	WELL	DG	11/03/2016	LO	123-38105	Woolley Becky 2F-7H-E168	DG
434335	WELL	DG	10/23/2016	LO	123-38106	Woolley Sosa 2D-7H-E168	DG
434336	WELL	DG	11/01/2016	LO	123-38107	Woolley Becky 2D-7H-E168	DG
434337	WELL	DG	10/18/2016	LO	123-38108	Woolley Sosa 2B-7H-E168	DG
434338	WELL	DG	10/30/2016	LO	123-38109	Woolley Becky 2B-7H-E168	DG
434339	WELL	DG	10/24/2016	LO	123-38110	Woolley Sosa 2E-7H-E168	DG
434340	WELL	DG	10/29/2016	LO	123-38111	Woolley Becky 2A-7H-E168	DG
434341	WELL	DG	11/02/2016	LO	123-38112	Woolley Becky 2E-7H-E168	DG
434342	WELL	DG	10/26/2016	LO	123-38113	Woolley Sosa 2F-7H-E168	DG
434343	WELL	DG	11/05/2016	LO	123-38114	Woolley Becky 2H-7H-E168	DG
436731	WELL	DG	10/31/2016	LO	123-39241	Woolley Becky 2C-7H-E168	DG
436733	WELL	DG	11/04/2016	LO	123-39242	Woolley Becky 2G-7H-E168	DG
436738	WELL	DG	10/19/2016	LO	123-39245	Woolley Sosa 2C-7H-E168	DG

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	PPROX 32' SOUND WALLS AROUND LOCATION		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Field Flare	
Comment:	NOT IN USE AT TIME OF INSPECTION	
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>434333</u>	Type: <u>WELL</u>	API Number: <u>123-38104</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434334</u>	Type: <u>WELL</u>	API Number: <u>123-38105</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434335</u>	Type: <u>WELL</u>	API Number: <u>123-38106</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434336</u>	Type: <u>WELL</u>	API Number: <u>123-38107</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434337</u>	Type: <u>WELL</u>	API Number: <u>123-38108</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434338</u>	Type: <u>WELL</u>	API Number: <u>123-38109</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434339</u>	Type: <u>WELL</u>	API Number: <u>123-38110</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434340</u>	Type: <u>WELL</u>	API Number: <u>123-38111</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434341</u>	Type: <u>WELL</u>	API Number: <u>123-38112</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434342</u>	Type: <u>WELL</u>	API Number: <u>123-38113</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434343</u>	Type: <u>WELL</u>	API Number: <u>123-38114</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>436731</u>	Type: <u>WELL</u>	API Number: <u>123-39241</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>436733</u>	Type: <u>WELL</u>	API Number: <u>123-39242</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>436738</u>	Type: <u>WELL</u>	API Number: <u>123-39245</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>

Complaint

Comment: Complaint #: 200441103

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 2-17-2017 Time 0800 Hrs

Contacted by Inspector:

Date: 2-17-2017 Time 0941 Hrs

Well Number#: Location #: 305447

Inspection Document #: 672500413

Complainant: Elieen Rojas Phone: 617-335-3508

Address: 1358 Washburn St , Erie CO 80516

Nature of complaint: Noise

Field Inspector Actions:

On 2-17-2017, I was contacted by James Precup NE supervisor of the COGCC in reference to a noise complaint at the residence of the complainant Elieen Rojas 1358 Washburn St Erie.

I performed a complete site inspection of the location on 2-17-2017. At the time of inspection, I reviewed location records, which did not show any abnormal drilling conditions at the time of the complaints. I also reviewed Environmental Noise Control Inc. continuous sound study information.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

No violations of COGCC rules were observed at the time of the inspection.

Corrective Action:

Date:

Well Drilling

Rig: Rig Name: Ensign Pusher/Rig Manager: Robert

Permit Posted: Access Sign:

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES

Pressure Test BOP: Pass Test Pressure PSI: Safety Plan: YES

Drill Fluids**Management:**

Lined Pit: Unlined Pit: Closed Loop: YES Semi-Closed Loop:

Multi-Well: YES Disposal Location: waste connection

Comment: All lighting on location pointed down and toward the center of location

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: not in use at time of inspection

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass			Vehicle Tracking		
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Rip Rap	Pass					
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT