Inspector Name: CONKLIN, CURTIS

FORM INSP Rev

X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/24/2017
Submitted Date:

03/24/2017

Document Number:

675204067

FIELD INSPECTION FORM

Loc ID Inspector Name:		ne:	On-Site Inspection				<u>Statu</u>	is Summary:				
446582	146582 CONKLIN, CURTIS		2A Doc Num:				THIS IS A FOLLOW UP INSPECTION					
Operator Information:							FOLLOW UP INSPECTION REQUIRED					
OGCC Oper	ator Number:	10447					X	IO FOLLOW UP INSPECTION F	REQUIRED			
Name of Operator: URSA OPERATING COMPANY LLC								Findings:				
Address: 1050 17TH STREET #1700							5 Number of Comments					
City:	DENVER	State: CO Zip: 80265 Onrective Action Response Requested										
Contact Information:												
Contact Name		Phon	e I	Email			Comment					
Knudson, Dwayne		(970)		dknudson@ursaresources m			s.co	co All Inspections				
Lind, Jennifer		(720)	508-8362 j	jlind@ursaresources.com				All Inspections				
Inspected Fa	acilities:											
Facility ID	Туре	Status	Status Date	Well C	lass	API Num		Facility Name	Insp Status			
446581	WELL	XX	07/14/2016			045-23270		BMC D 32B-18-07-95	DG			

General Comment:

Drilling inspection. Notifications have been received for Spud and cement to date.

Inspector Name: CONKLIN, CURTIS **Location** Overall Good: X Signs/Marker: Type DRILLING/RECOMP Comment: Corrective Action: Date: Emergency Contact Number: Comment: Corrective Action: Date: Overall Good: X Spills: Туре Area Volume In Containment: No Comment: Multilple Spills and Releases? Fencing/: Type LOCATION Comment: Sound wall in place Corrective Action: Date: Venting: Yes/No NO Comment: Corrective Action: Date: Flaring: Туре Comment: Corrective Action: Date:

Inspector Name: CONKLIN, CURTIS

Inspected Facilities												
Facility ID: 446	5581 Type: _	WELL	API Number:	045-23270	Status: _	XX	Insp. Status:	DG				
			Well Dri	lling								
	me: Capstar 321		Pusher/Rig Manage	r: Richard McNei	il							
Permit Posted: Yes Access Sign: Yes												
Well Control Equipment:												
Pipe Ram: Blind Ram: Hydril Type:												
Pressure Test BOP: Test Pressure PSI: Safety Plan: YES												
Drill Fluids												
Lined	Pit:	Unlined I	Pit:	Closed Loop:	YES	Semi-	Closed Loop:					
Multi-W	/ell: YES	Disposal Loca	ation: On location									
<u>Comm</u>	ent: Drilling surface	e at time of ins	spection.									
Corrective Act	on:						Date:					
Attached Documents												
You can go to C	OGCC Images (<u>h</u>	nttps://cogcc	.state.co.us/weblin	k/) and search b	by documer	nt number:						
Document Num	Description	-	URL		-							
401243151	INSPECTION		http://ogccweblink.st	ate.co.us/Downlo	adDocumen	tPDF.aspx?	DocumentId=4108	<u>637</u>				
	SUBMITTED											