Inspector Name: CONKLIN, CURTIS

FORM INSP

X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



FIELD INSPECTION FORM

Loc ID Inspector Name:			On-Site Inspection				Status Summary:					
446582	CONKLIN, CURTIS			2A Doc Num:			☐ THIS IS A FOLLOW UP INSPECTION					
Operator Information:							FOLLOW UP INSPECTION REQUIRED					
OGCC Operator Number: 10447								NO FOLLOW UP INSPECTION REQUIRED				
Name of Operator: URSA OPERATING COMPANY LLC								Findings:				
Address 4050 47TH OTDEET #4700								5 Number of Comments				
Address: 1050 17TH STREET #1700								0 Number of Corrective Actions				
City:	DENVER	State: CO Zip: 80265					Corrective Action Response Requested					
Contact Info	ormation:											
Contact Na	me	Phon	е	Email			Comment					
Knudson, E	wayne	(970)	456-3335	dknudson@ursaresource m			es.co All Inspections					
Lind, Jennifer		(720)	508-8362	jlind@ursaresources.com			All Inspections					
Inspected F	acilities:											
Facility ID	Туре	Status	Status Date	e Well Class		API Num		Facility Name	Insp Status			
446581	WELL	XX	07/14/2016			045-2327	7 0	BMC D 32B-18-07-95	DG			
General Cor	nment:											
Drilling insp	ection. Notification	ns have be	een received fo	or Spud and	cemen	t to date.						

Inspector Name: CONKLIN, CURTIS **Location** Overall Good: X Signs/Marker: Type DRILLING/RECOMP Comment: Corrective Action: Date: Emergency Contact Number: Comment: Corrective Action: Date: Overall Good: X Spills: Туре Area Volume In Containment: No Comment: Multilple Spills and Releases? Fencing/: Type LOCATION Comment: Sound wall in place Corrective Action: Date: Venting: Yes/No NO Comment: Corrective Action: Date: Flaring: Туре Comment: Corrective Action: Date:

Inspector Name: CONKLIN, CURTIS

Inspected Facilities											
Facility ID: 446	5581 Type: _	WELL	API Number:	045-23270	Status: _	XX	Insp. Status:	DG			
			Well Dri	lling							
	me: Capstar 321		Pusher/Rig Manage	r: Richard McNei	il						
Permit Posted: Yes Access Sign: Yes											
Well Control Equipment:											
Pipe Ram: Blind Ram: Hydril Type:											
Pressure Test BOP: Test Pressure PSI: Safety Plan: YES											
Drill Fluids ————————————————————————————————————											
Lined	Pit:	Unlined I	Pit:	Closed Loop:	YES	Semi-	Closed Loop:				
Multi-W	/ell: YES	Disposal Loca	ation: On location								
<u>Comm</u>	ent: Drilling surface	e at time of ins	spection.								
Corrective Act	on:						Date:				
Attached Documents											
You can go to C	OGCC Images (<u>h</u>	nttps://cogcc	.state.co.us/weblin	k/) and search b	by documer	nt number:					
Document Num	Description	-	URL		-						
401243151	INSPECTION		http://ogccweblink.st	ate.co.us/Downlo	adDocumen	tPDF.aspx?	DocumentId=4108	<u>637</u>			
	SUBMITTED										