



photo 1: Facing southwest along the access road. The sides of the road were recently seeded and mulched.



photo 2: Facing northeast along the access road. The sides of the road were recently seeded and mulched.



photo 3: Facing west toward the location.



photo 4: The water level is nearing the 2 ft. freeboard marker.