Inspector Name: LONGWORTH, MIKE

FORM INSP State of Colorado
Oil and Gas Conservation Commission

DNR CO

Inspection Date:

03/27/2017
Submitted Date:

03/28/2017

Document Number: 674703778

Rev X/15 Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109

## FIELD INSPECTION FORM

Loc ID Inspector Name:		On-S	ite Inspection			s Summary:		
324381 L	ONGWORTH, M	IKE	2A Doc Num:		T	HIS IS A FOLLOW UP INSPECTION		
Operator Informa	ation:				F(	OLLOW UP INSPECTION REQUIRED		
OGCC Operator N	Number: 96	8850			▼ N	O FOLLOW UP INSPECTION REQUIRED		
Name of Operator: TEP ROCKY MOUNTAIN LLC								
Address: PO BOX 370						0 Number of Comments		
7 dai 033. 1 0 00	7, 07 0				0	Number of Corrective Actions		
City: PARA	CHUTE St	ate: CO	Zip: _	81635	Co	orrective Action Response Requested		
Contact Informat	ion:							
Contact Name		Phone	Email			Comment		
Inspection, Terra	а ТЕР	970-263-2716	COGCCIr erraep.co	nspectionReport m	s@t			

Inspected Fa	acilities:						
Facility ID	Туре	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448065	WELL	DG	01/29/2017		045-23341	Chevron TR 314-21-597	DG

## **General Comment:**

Inspector Name: LONGWORTH, MIKE **Location** Lease Road: Type Access comment: Corrective ActionL Date: Overall Good: X Signs/Marker: Type DRILLING/RECOMP Comment: Corrective Action: Date: **Emergency Contact Number:** Comment: Corrective Action: Date: **Good Housekeeping:** Type STORAGE OF SUPL Comment: Corrective Action: Date: Overall Good: X Spills: Туре Area Volume In Containment: No Comment: Multilple Spills and Releases? Venting: Fla Ту

Yes/No	NO		
Comment:			
Corrective Action:		Date:	
aring:			
/ре			
Comment			
Corrective Action:		Date:	
Date Run: 4/5/201	7 Doc [#674703778]		Page 2 of 4

Inspector Name: LONGWORTH, MIKE

Inspected Facilities							
Facility ID: 448065 Type:	WELLA	Number: _	045-23341	Status: _	DG	Insp. Status:	DG
		Well Dril					
Rig: Rig Name: H&P 271	Pushe		: Jayson Boebert	<u> </u>			
Permit Posted: Yes		Access Sign	: Yes				
Well Control Equipment: Pipe Ram:	Blind Ram:	Hydril	Type:				
	Test Pressure PSI:	<del></del>	ety Plan:				
Drill Fluids Management:	_		YES	_			
Lined Pit:	Unlined Pit:		Closed Loop: _	YES	Semi	-Closed Loop:	
Multi-Well: YES	Disposal Location:						
Comment:							
Corrective Action:						Date:	

Inspector Name: LONGWORTH, MIKE

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
				Covering Materials	Pass	
Comment:						Date:
Corrective Action:  Date:  Pits: NO SURFACE INDICATION OF PIT						

## **Attached Documents**

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
401246214	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4111415

Date Run: 4/5/2017 Doc [#674703778]