



**photo 1:** Facing northeast toward the location.



**photo 2:** There is a pipe riser which remains at the access road near the southwest side of the location.



**photo 3:** Facing east toward the location.



**photo 4:** Facing northwest at the location.



**photo 5:** Facing east along the north fill slope.



**photo 6:** Northeast side of the location facing southwest.



**photo 7:** East side of the location facing southwest.



**photo 8:** South side of the location facing northwest.