

# Final Reclamation Inspection

April 27, 2017

Operator: SLAWSON EXPLORATION COMPANY INC- #10334

API: 05-123-31858

Weld County, CO

SESE Section 26 T12N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Chuckwagon #26-12-67  
API: 05-123-31858



**Photo 1.** Photo taken from the approximate center of location, facing West. No evidence of disturbance at location, confirming the location was never constructed.



**Photo 2.** Photo taken from the approximate center of location, facing North. No evidence of disturbance at location, confirming the location was never constructed.

Inspection Photos  
Location Name: Chuckwagon #26-12-67  
API: 05-123-31858



**Photo 3.** Photo taken from the approximate center of location, facing East. No evidence of disturbance at location, confirming the location was never constructed.



**Photo 4.** Photo taken from the approximate center of location, facing South. No evidence of disturbance at location, confirming the location was never constructed.