

Inspection Photos
Location AMBUSH 24-22
API:05-001-09106



WELL SIGN



SOILED DIRT INSIDE PUMP JACK HOUSE