

Final Reclamation Inspection

October 4, 2017

Operator: ANADARKO E&P ONSHORE LLC- 2800

API: 05-123-31711

Weld County, CO

SWNE Section 3 T9N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HUTCHISON #9-67-3-7
API: 05-123-31711



Photo 1. Photo taken from the eastern well location, facing West. Unable to find evidence of oil and gas activities and/or disturbances. Well location appears reflective of reference areas. Crested wheatgrass (*Agropyron cristatum*) does appear to be at a higher density than reference areas but Blue grama (*Bouteloua gracilis*) was observed within the reclamation area.



Photo 2. Photo taken from the eastern well location, facing East along the access road. Crested wheatgrass does appear to be at a higher density along the access road than reference areas but Blue grama was observed within the reclamation area.

Inspection Photos
Location Name: STATE #2-16-1
API: 05-123-31432



Photo 3. Reference photo taken just south of the location, facing South. Well location and access road appear reflective of reference areas. Crested wheatgrass does appear to be at a higher density within the reclamation areas but Blue grama- which is the dominant vegetative cover in reference areas- was observed within the reclamation areas.